


CHART 1: Capacity on site and incidents affecting capacity



B: Break-in **C**: Crane failure **C**: Compactor failure **F**: Fire **N**: Non-conforming waste incident **P**: Mobile plant failure **T**: No train **T**: Light train **X**: Site closure **W**: Fire system works
C: Container failures

— Forecast
 — Amber Capacity
 — Actual
 — Red Capacity
 — Green Capacity

CHART 2: Turnaround Times Victoria Road – All boroughs Aug – Oct 2023






CHART 3: No. visits Apr-Oct by turnaround time

Year

Multiple selections

Month

Multiple selections

Day

All

Site

Victoria Road

Waste Type

Residual Waste

Shipping Account

Multiple selections All boroughs

Ref 2

All

Parameter

All

00:00 - 10:00

60,075

10:00 - 15:00

17,400

15:00 - 20:00

9,479

20:00 - 25:00


5,363

25:00 - 35:00

4,883

35:00+

2,877



Year
2023

Month
Multiple selections

Day
All

Site
Victoria Road

Waste Type
Residual Waste

Shipping Account
Multiple selections

Parameter
Shipping Account

Net Tonnes

By Arrival Time (Nearest 15 Minutes)

